

Icons

ADAS Diagnostic

Enabled



Disabled




Not working optimally¹




¹ Because of: heavy rain, bad exposure, low visibility, low image quality, excessive movement.

ADAS Calibration


Device Height (high / low)




Device Pitch (down / up)



Device Roll (left/ right)




Device Yaw (left/ right)




ADAS Lane Departure


Left Dashed




Left Solid



Right Dashed



Right Solid



ADAS Pedestrian

Collision



ADAS Vehicle


Collision



Dangerous Headway



Moving Traffic



Nearby Vehicle

